TSUNEISHI ENGINEERING CO.,LTD.

HATCH COVER NEWS #000



<u>ハッチカバー特設サイト新設について</u>

この度、ハッチカバーの特設サイトを新設、公開しましたことをお知らせいたします。弊社は2009年5月に初納入して以来、毎年着実に納入実績を重ね、来年2023年には引き渡し実績が600隻を超えようとしております。本サイトではそのタイプ別ラインナップに加え、弊社が日頃より心がけている懇切、丁寧なカスタマーサービスについても掲載しております。

また、ニュースを定期的に更新し、これまでお客様よりご報告いただいた損傷事例などをご紹介して、本船の保 守点検やミスオペレーション防止のご参考にしていただければと考えております。問い合わせ窓口も併設しており ますので、本サイトを通じてお気軽にお問い合わせください。

以下、今後掲載予定のニュースのトピックの一例をご紹介いたします。

記

- 1. BALLAST HOLD HATCH COVERの VACUUM 事故について
- 2. ワイヤーおよびチェーンの点検について
- 3. レストパッドおよびウェッジガイドの点検、補修について
- 4. シリンダーラム保護カバーについて
- 5. シリンダーピンの発錆、固着防止について
- 6. ホールシャフトの発錆、固着防止について

以上

・お問い合わせ窓口

常石エンジニアリング (https://tsune-e.com/product/contact) または (tet.hcv@tsuneishi.com) または 084-987-1445)



TSUNEISHI ENGINEERING CO.,LTD.

HATCH COVER NEWS #000



Hatch Cover Website Newly Launched

Over 600 vessels will have been being equipped with our hatch cover and traversing to the global ocean since our first product was delivered on May 2009. The hatch cover website is hereby newly launched. This site includes the selection of different hatch cover products by type, customer service & support, which is our top priority.

The news will be regularly updated including accident reports. We aspire that this will help for the maintenance and caution of mis-operation of our customers' vessels. The below is the example of the topics planned to be uploaded in near future.

- NEWS TOPICS -

- 1. Vacuum accident of ballast hold
- 2. Inspection of chain & wire
- 3. Inspection and maintenance of rest pad and wedge guide
- 4. Protection covers for hydraulic jack cylinder ram
- 5. Corrosion and stuck of hydraulic jack cylinder pin for end folding type hatch cover
- 6. Corrosion and stuck of wheel spindle for end folding type hatch cover

Feel free to contact us thru the query form attached on the site.

Customer Service Desk

TSUNEISHI ENGINNERING CO., LTD. (https://tsune-e.com/product/contact/en OR te.hcv@tsuneishi.com)
OR +81(0)84-987-1445)

